



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION II

JACOB K. JAVITS FEDERAL BUILDING
NEW YORK, NEW YORK 10278

12.02-9/6/91-00188

SEP 8 1991

CERTIFIED MAIL
RETURN RECEIPT REQUESTED

Mr. Paul A. Rakowski, P.E.
Environmental Programs Branch
Atlantic Division, Code 182
Naval Facilities Engineering Command
Norfolk, VA 23511-6287


Dear Mr. Rakowski:

Re: NAVSTA Roosevelt Roads - EPA I.D. No. PR2170027203

This letter is offered as clarification to certain points discussed in the meeting with Region II staff in New York on September 4, 1991. Please be advised that in order for any ongoing corrective action measures undertaken at NAVSTA Roosevelt Roads to satisfy RCRA requirements, clean-up must meet the action levels given in Subpart S, "Corrective Action for Solid Waste Management Units (SWMUs) at Hazardous Waste Management Facilities" published in the Federal Register of July 27, 1990.

These may or may not be the same as CERCLA action levels. Should you have any questions on this issue, please contact Mr. Timothy Gordon of my staff, at (212) 264-5133.

Sincerely yours,


Michael Poetzsch, Chief
Caribbean Facilities Section

cc. R. E. Ybanez, NAVSTA Roosevelt Roads
F. Feliciano, NAVSTA Roosevelt Roads
Teresa del Colon, EQB